
# FPV frame Assembly Guide for Sector 5 V3




## Screw list for Sector 5 V3


| | | |
|---|---|---|
| 1 | M3x25mm Screw | 5 |
| 2 | M3x16mm Screw | 4 |
| 3 | M3x12mm Screw | 4 |
| 4 | M3x8mm Screw | 12 |
| 5 | M3x6mm Screw | 2 |
| 6 | M2x30mm Screw | 1 |
| 7 | M2x25mm Screw | 4 |
| 8 | M2x6mm Screw | 2 |
| 9 | M2x4mm Screw | 2 |


## Aluminum column list for Sector 5 V3


| | | |
|---|---|---|
| 10 | M3x32mm Screw | 2 |
| 11 | M3x25mm Screw | 6 |
| 12 | M3x23mm Screw | 3 |


## TPU list for Sector 5 V3




⑤
⑤


M3x23mm
M3x23mm
⑫
⑫


③
②
②
③
②
③


M3x25mm
①